

Health Occupations

Linn-Benton CC

Linn_coc03A

Building Type Community_College	County Linn	
Street 6500 SW Pacific Blvd		
City Albany	State OR	Zip 97321
Latitude 44.58667	Longitude 123.11473	
Tracking Code Miller 2004-05	Inspection Date 5/13/2004	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	2.5	-1.5	-0.5	0	0	0	-0.6	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Health Occupations

Final RVS Score

Final Type	Final Score
C1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Health Occupations

Linn_coc03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
16698	1973	1973	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
16698	2	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
Falling Hazards		Poor Conditions	
None			
None			
None			



S General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries