

Science and Technology

Linn_coc06A

Linn-Benton CC

Building Type		County	
Community_College		Linn	
Street			
6500 SW Pacific Blvd			
City	State	Zip	
Albany	OR	97321	
Latitude	Longitude		
44.58726	123.11472		
Tracking Code	Inspection Date		
Miller 2004-05	5/13/2004		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	2.5	-1.5	-0.5	0	0	0	-0.6	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Science and Technology

Final RVS Score

Final Type


Final Score

C1

-0.1

FEMA-154 Collapse Potential

Very High (100%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1973	1973	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
32658	2	No	No

Plan Irregularities	Vertical Irregularities
None	None

Falling Hazards	Poor Conditions
None	
None	
None	



S General Site



S General Site

