

Takena Hall

Linn-Benton CC

Linn_coc09A

Building Type		County	
Community_College		Linn	
Street			
6500 SW Pacific Blvd			
City	State	Zip	
Albany	OR	97321	
Latitude	Longitude		
44.58661	123.11394		
Tracking Code	Inspection Date		
Miller 2004-05	5/13/2004		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC2	2.4	-1	-0.5	0	0	0	-0.6	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Takena Hall

Final RVS Score

Final Type


Final Score

PC2

0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1979	1979	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
50387	2	No	No

Plan Irregularities	Vertical Irregularities
Yes: Unknown	Yes: Unknown

Falling Hazards	Poor Conditions
None	
None	
None	



S General Site