

South Santiam Hall

Linn-Benton CC

Linn_coc11A

Building Type	County	
Community_College	Linn	
Street		
6500 SW Pacific Blvd		
City	State	Zip
Albany	OR	97321
Latitude	Longitude	
44.58749	123.11314	
Tracking Code	Inspection Date	
RVS in 2006	8/19/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C1	2.5	0	0	0	0	0	-0.6	0	1.9
Secondary	RM2	2.8	0	0	0	0	0	-0.6	0	2.2
Tertiary		0	0	0	0	0	0	0	0	0


South Santiam Hall

Final RVS Score

Final Type	Final Score
C1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



REV 6/05



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

South Santiam Hall

Linn_coc11A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1973	1973	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
None		None	
None		None	
			
S	General Site	S	Primary Structural Type
			
E	General Site		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries