

Luckiamute Center

Linn-Benton CC

Linn_coc12A

Building Type Community_College	County Linn	
Street 6500 SW Pacific Blvd		
City Albany	State OR	Zip 97321
Latitude 44.58914	Longitude 123.11563	
Tracking Code New Building	Inspection Date 3/1/2007	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Luckiamute Center

Final RVS Score

Final Type
Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	2004	2004	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	