

Harrisburg Fire & Rescue - Station 41

Harrisburg Fire & Rescue

Linn_fir06A

Building Type	County	
Fire - RFPD	Linn	
Street		
500 Smith St		
City	State	Zip
Harrisburg	OR	97446
Latitude	Longitude	
44.27203	123.16811	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC2	2.4	-1	0	0	0	0	-0.6	0	0.8
Secondary	S3	3.2	0	0	0	0	0	-0.6	0	2.6
Tertiary	PC1	2.6	0	0	0	0	0	-0.6	0	2

Harrisburg Fire & Rescue - Station 41

Final RVS Score

Final Type	Final Score
PC2	0.8

FEMA-154 Collapse Potential

High (>10%)



Harrisburg Fire & Rescue - Station 41

Linn_fir06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1950	1950	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE Plan Irregularity Secondary		E Vertical Irregularity Primary	
		W Plan Irregularity Primary S3 addition shown	