

Tangent RFPD

Linn_fir08A

Tangent RFPD

Building Type		County	
Fire - RFPD		Linn	
Street			
32053 Birdfoot Dr			
City	State	Zip	
Tangent	OR	97389	
Latitude	Longitude		
44.54146	123.1077		
Tracking Code	Inspection Date		
RVS in 2006	6/30/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	0	0	2.4	0	-0.8	0	3.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Tangent RFPD

Final RVS Score

Final Type

Final Score

W2

3.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1989	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent
Torsion: Eccentric Stiffness	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S Vertical Irregularity Primary
torsion - eccentric stiffness



S Plan Irregularity Primary

