

Halsey-Shedd RFPD

Halsey-Shedd RFPD

Linn_fir20A

| | | |
|------------------------------|------------------------------|--------------|
| Building Type Fire - RFPD | County Linn | |
| Street 31919 Oakville Dr | | |
| City Shedd | State OR | Zip 97377 |
| Latitude 44.51011 | Longitude 123.18714 | |
| Tracking Code RVS in 2006 | Inspection Date 6/30/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | S3 | 3.2 | 0 | 0 | 0 | 0 | 0 | -0.6 | 0 | 2.6 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Halsey-Shedd RFPD

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| S3 | 2.6 |

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------------------------------------------------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1990 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | No | No |
| Plan Irregularities | | Vertical Irregularities | |
| None | | None | |
| None | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  | | | |
| NE General Site | | | |

