

# Jefferson RFPD

Jefferson RFPD

Linn\_fir27A

|                  |                 |       |
|------------------|-----------------|-------|
| Building Type    | County          |       |
| Fire - RFPD      | Linn            |       |
| Street           |                 |       |
| 4310 Woods Rd NE |                 |       |
| City             | State           | Zip   |
| Millersburg      | OR              | 97321 |
| Latitude         | Longitude       |       |
| 44.68223         | 123.07664       |       |
| Tracking Code    | Inspection Date |       |
| RVS in 2006      | 6/30/2006       |       |



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | W2   | 3.8         | 0          | -0.5       | 0        | 0          | -0.4   | 0      | 0      | 2.9       |
| Secondary | RM1  | 2.8         | 0          | -0.5       | 0        | 0          | -0.4   | 0      | 0      | 1.9       |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Jefferson RFPD

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1        | 1.9         |

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

|  |                             |                          |                    |
|--|-----------------------------|--------------------------|--------------------|
| Enrollment   | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
|  |                             |                          | 1970               |
| Total Area (square ft)   | Number of Stories           | Basement                 | Pounding Potential |
|  | 1                           | No                       | No                 |
| Plan Irregularities  |                             | Vertical Irregularities  |                    |
| Torsion: Eccentric Stiffness   |                             | None                     |                    |
| None   |                             | None                     |                    |
| None   |                             | None                     |                    |
| Falling Hazards  |                             | Poor Conditions          |                    |
| None   |                             | None                     |                    |
| None   |                             | None                     |                    |
| None   |                             | None                     |                    |
|                      |                             |                          |                    |
| W General Site<br>This picture shows a large CMU wall on the opposite side of the large door openings. |                             |                          |                    |