

Samaritan Albany General Hospital

Samaritan Health Services NFP

Linn_hos01A

Building Type Hospital	County Linn	
Street 1046 6th Ave SW		
City Albany	State OR	Zip 97321
Latitude 44.6316	Longitude 123.1162	
Tracking Code New Building	Inspection Date 6/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S4	3.2	-1	0	0	0	-0.4	0	0	1.8
Secondary	S1	3	-1	0	0	0	-0.4	0	0	1.6
Tertiary	C1	2.9	-1.5	0	0	0	-0.4	0	0	1


Samaritan Albany General Hospital

Final RVS Score

Final Type	Final Score
C1	1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Samaritan Albany General Hospital

Linn_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1965	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
115820	4	Yes	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Heavy Cladding (thick stone or concrete)		None	
None		None	
None		None	
			
NE	General Site	N	Primary Structural Type Also Cladding (solid concrete awnings) ..I beam -shaped pieces.
		E	Vertical Irregularity Primary
		Plan irregularity	
S	Secondary Structural Type	E	Secondary Structural Type
		E	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries