

# Samaritan Lebanon Community Hospital

Samaritan Health Services NFP

Linn\_hos02A

Building Type Hospital	County Linn	
Street 525 N Santiam Hwy		
City Lebanon	State OR	Zip 97355
Latitude 44.55097	Longitude 122.90713	
Tracking Code New Building	Inspection Date 7/31/2006	



Seismicity Zone: Moderate

**FEMA 154 Rapid Visual Screening Score Card**

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	RM2	3.4	-1.5	-0.5	0	0	0	-1.2	0	0.2
Tertiary		0	0	0	0	0	0	0	0	0


**Samaritan Lebanon Community Hospital**

**Final RVS Score**

Final Type RM1	Final Score -0.1
-------------------	---------------------

**FEMA-154 Collapse Potential**

Low (<1%)
-----------



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Samaritan Lebanon Community Hospital

Linn\_hos02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1951	1951	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: Other		None	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N General Site			

# Samaritan Lebanon Community Hospital

Samaritan Health Services NFP

Linn\_hos02B

Building Type	County	
Hospital	Linn	
Street		
525 N Santiam Hwy		
City	State	Zip
Lebanon	OR	97355
Latitude	Longitude	
44.55104	122.90673	
Tracking Code	Inspection Date	
New Building	7/31/2006	

Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	RM2	3.4	-1.5	-0.5	0	0	0	-1.2	0	0.2
Tertiary		0	0	0	0	0	0	0	0	0


Samaritan Lebanon Community Hospital

## Final RVS Score

Final Type	Final Score
RM1	-0.1

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Samaritan Lebanon Community Hospital

Linn\_hos02B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1957	1951	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Samaritan Lebanon Community Hospital

Samaritan Health Services NFP

Linn\_hos02C

Building Type	County	
Hospital	Linn	
Street		
525 N Santiam Hwy		
City	State	Zip
Lebanon	OR	97355
Latitude	Longitude	
44.55084	122.90689	
Tracking Code	Inspection Date	
New Building	7/31/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Samaritan Lebanon Community Hospital

**Final RVS Score**

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Low (<1%)
-----------



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Samaritan Lebanon Community Hospital

Linn\_hos02C

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1960	1951	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: U shaped		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E General Site			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Samaritan Lebanon Community Hospital

Samaritan Health Services NFP

Linn\_hos02D

Building Type	County	
Hospital	Linn	
Street		
525 N Santiam Hwy		
City	State	Zip
Lebanon	OR	97355
Latitude	Longitude	
44.55156	122.90718	
Tracking Code	Inspection Date	
New Building	7/31/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	RM2	3.4	-1.5	-0.5	0	0	0	-1.2	0	0.2
Tertiary		0	0	0	0	0	0	0	0	0


Samaritan Lebanon Community Hospital

**Final RVS Score**

Final Type	Final Score
RM1	-0.1

**FEMA-154 Collapse Potential**

Low (<1%)
-----------



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Samaritan Lebanon Community Hospital

Linn\_hos02D

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1961	1951	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N General Site Also shows building A.			

# Samaritan Lebanon Community Hospital

Samaritan Health Services NFP

Linn\_hos02E

Building Type	County	
Hospital	Linn	
Street		
525 N Santiam Hwy		
City	State	Zip
Lebanon	OR	97355
Latitude	Longitude	
44.55132	122.90721	
Tracking Code	Inspection Date	
New Building	7/31/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	RM2	3.4	-1.5	-0.5	0	0	0	-1.2	0	0.2
Tertiary		0	0	0	0	0	0	0	0	0


Samaritan Lebanon Community Hospital

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Low (<1%)
-----------



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Samaritan Lebanon Community Hospital

Linn\_hos02E

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1986	1951	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Samaritan Lebanon Community Hospital

Samaritan Health Services NFP

Linn\_hos02F

Building Type Hospital	County Linn	
Street 525 N Santiam Hwy		
City Lebanon	State OR	Zip 97355
Latitude 44.55122	Longitude 122.90681	
Tracking Code New Building	Inspection Date 7/31/2006	

Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Samaritan Lebanon Community Hospital

## Final RVS Score

Final Type	Final Score
RM1	2.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Samaritan Lebanon Community Hospital

Linn\_hos02F

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1988	1951	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	

# Samaritan Lebanon Community Hospital

Samaritan Health Services NFP

Linn\_hos02G

Building Type Hospital	County Linn	
Street 525 N Santiam Hwy		
City Lebanon	State OR	Zip 97355
Latitude 44.55143	Longitude 122.9065	
Tracking Code New Building	Inspection Date 7/31/2006	



Seismicity Zone: Moderate

**FEMA 154 Rapid Visual Screening Score Card**

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM2	3.4	-1.5	-0.5	0	1.8	0	-1.2	0	2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


**Samaritan Lebanon Community Hospital**

**Final RVS Score**

Final Type	Final Score
RM2	2

**FEMA-154 Collapse Potential**

Low (<1%)
-----------



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Samaritan Lebanon Community Hospital

Linn\_hos02G

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1993	1951	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: Other		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	

# Samaritan Lebanon Community Hospital

Samaritan Health Services NFP

Linn\_hos02H

Building Type Hospital	County Linn	
Street 525 N Santiam Hwy		
City Lebanon	State OR	Zip 97355
Latitude 44.55143	Longitude 122.90623	
Tracking Code New Building	Inspection Date 7/31/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C3	3.2	-2	-0.5	0	0	0	-1	0	-0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Samaritan Lebanon Community Hospital

**Final RVS Score**

Final Type	Final Score
C3	-0.3

**FEMA-154 Collapse Potential**

Low (<1%)
-----------



# Samaritan Lebanon Community Hospital

Linn\_hos02H

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1988	1951	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N General Site			