

Linn County

| | | |
|-----------------|--------|-----------------|
| Building Type | County | |
| Police - County | Linn | |
| Street | | |
| 354 Smith St. | | |
| City | State | Zip |
| Harrisburg | OR | 97446 |
| Latitude | | Longitude |
| 44.2721 | | 123.17022 |
| Tracking Code | | Inspection Date |
| RVS in 2006 | | 7/7/2006 |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | C2 | 2.8 | 0 | -0.5 | -1 | 0 | 0 | -0.6 | 0 | 0.7 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Linn County Sheriff's Office

Final RVS Score

Final Type

Final Score

C2

0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1930 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | No | No |

| | |
|--------------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| Reentrant Corners: Other | None |
| None | None |
| None | None |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None | None |
| None | None |
| None | None |



NE Plan Irregularity Primary

