

Harrisburg Elementary School

Harrisburg SD 7J

Linn_sch14A

Building Type	County	
School	Linn	
Street		
642 Smith St		
City	State	Zip
Harrisburg	OR	97446
Latitude	Longitude	
44.2715	123.1657	
Tracking Code	Inspection Date	
RVS in 2006	7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	0	-0.6	0	-0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg Elementary School

Final RVS Score

Final Type	Final Score
C2	-0.3

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Harrisburg Elementary School

Linn_sch14A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
408	1936	1949	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
32854	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		Cracks	
None		None	
None		None	
			
S Primary Structural Type		W Vertical Irregularity Primary	W Vertical Irregularity Primary
			
			
E Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harrisburg Elementary School

Harrisburg SD 7J

Linn_sch14B

Building Type	County
School	Linn
Street	
201 S 6th St	
City	State Zip
Harrisburg	OR 97446
Latitude	Longitude
44.27101	123.16534
Tracking Code	Inspection Date
RVS in 2006	7/31/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Harrisburg Elementary School

Linn_sch14B

Enrollment 408	Year Built (Field Verified) 1993	Year Built (Alt. Source) 1949	Est. Decade Built 1990
Total Area (square ft) 32854	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
NE General Site			

Harrisburg Elementary School

Harrisburg SD 7J

Linn_sch14C

Building Type	County	
School	Linn	
Street		
201 S 6th St		
City	State	Zip
Harrisburg	OR	97446
Latitude	Longitude	
44.27083	123.1657	
Tracking Code	Inspection Date	
RVS in 2006	7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary	C2	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harrisburg Elementary School

Linn_sch14C

Enrollment 408	Year Built (Field Verified) 1949	Year Built (Alt. Source) 1949	Est. Decade Built 1950
Total Area (square ft) 32854	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	

Harrisburg Elementary School

Harrisburg SD 7J

Linn_sch14D

Building Type	County
School	Linn
Street	
201 S 6th St	
City	State Zip
Harrisburg	OR 97446
Latitude	Longitude
44.27148	123.16521
Tracking Code	Inspection Date
RVS in 2006	7/31/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Harrisburg Elementary School

Linn_sch14D

Enrollment 408	Year Built (Field Verified) 1949	Year Built (Alt. Source) 1949	Est. Decade Built 1970
Total Area (square ft) 32854	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S Primary Structural Type		N Plan Irregularity Primary Also shows covered playground.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harrisburg Elementary School

Harrisburg SD 7J

Linn_sch14E

Building Type	County	
School	Linn	
Street		
642 Smith St		
City	State	Zip
Harrisburg	OR	97446
Latitude	Longitude	
44.27202	123.16435	
Tracking Code	Inspection Date	
RVS in 2006	7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Harrisburg Elementary School

Linn_sch14E

Enrollment 408	Year Built (Field Verified) 1949	Year Built (Alt. Source) 1949	Est. Decade Built 1990
Total Area (square ft) 32854	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
NE Plan Irregularity Primary			

Harrisburg Elementary School

Harrisburg SD 7J

Linn_sch14F

Building Type	County
School	Linn
Street	
642 Smith St	
City	State Zip
Harrisburg	OR 97446
Latitude	Longitude
44.27195	123.16531
Tracking Code	Inspection Date
RVS in 2006	7/31/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg Elementary School

Final RVS Score

Final Type	Final Score
W2	0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Harrisburg Elementary School

Linn_sch14F

Enrollment 408	Year Built (Field Verified) 1959	Year Built (Alt. Source) 1949	Est. Decade Built 1950
Total Area (square ft) 32854	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Out of Plane Lateral-Force-Resistance Elements None		Vertical Irregularities Steps in Elevation View: Single Change Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None	
Falling Hazards None		Poor Conditions None	
None		None	
None		None	
			
N Plan Irregularity Primary		E Vertical Irregularity Primary	