

Foster Elementary School

Sweet Home SD 55

Linn_sch15A

| | | |
|-----------------|-----------------|-------|
| Building Type | County | |
| School | Linn | |
| Street | | |
| 5526 Poplar St. | | |
| City | State | Zip |
| Sweet Home | OR | 97386 |
| Latitude | Longitude | |
| 44.41042 | 122.67064 | |
| Tracking Code | Inspection Date | |
| RVS in 2006 | 7/3/2006 | |



| Seismicity Zone: Moderate | | | | | | | | | | |
|--|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| FEMA 154 Rapid Visual Screening Score Card | | | | | | | | | | |
| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
| Primary | W2 | 4.8 | -3 | -0.5 | 0 | 0 | 0 | -1.2 | 0 | 0.1 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Foster Elementary School

Final RVS Score

| | |
|------------|-------------|
| Final Type | Final Score |
| W2 | 0.1 |

FEMA-154 Collapse Potential

| |
|-------------|
| High (>10%) |
|-------------|



OregonGeology

Foster Elementary School

Linn_sch15A

| | | | |
|--|---|--|---------------------------|
| Enrollment 408 | Year Built (Field Verified) 1940 | Year Built (Alt. Source) 1940 | Est. Decade Built 1950 |
| Total Area (square ft) 39030 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities Reentrant Corners: U shaped Reentrant Corners: Other None | | Vertical Irregularities Steps in Elevation View: Single Change None None | |
| Falling Hazards Unreinforced Chimneys None None | | Poor Conditions None None None | |
|  |  |  | |
| NE General Site | NW Plan Irregularity Secondary | W Plan Irregularity Primary | |
|  | | | |
| N Falling Hazard | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Foster Elementary School

Sweet Home SD 55

Linn_sch15B

| | | |
|-----------------|-----------------|-------|
| Building Type | County | |
| School | Linn | |
| Street | | |
| 5526 Poplar St. | | |
| City | State | Zip |
| Sweet Home | OR | 97386 |
| Latitude | Longitude | |
| 44.41011 | 122.66999 | |
| Tracking Code | Inspection Date | |
| RVS in 2006 | 7/3/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | S3 | 3.8 | 0 | 0 | 0 | 0 | 0 | -1 | 0 | 2.8 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Foster Elementary School

Final RVS Score

| | |
|------------|-------------|
| Final Type | Final Score |
| S3 | 2.8 |

FEMA-154 Collapse Potential

| |
|-----------|
| Low (<1%) |
|-----------|



OregonGeology

Foster Elementary School

Linn_sch15B

| | | | |
|--|-------------------------------------|---|---------------------------|
| Enrollment 408 | Year Built (Field Verified) 1940 | Year Built (Alt. Source) 1940 | Est. Decade Built 1980 |
| Total Area (square ft) 39030 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities None None None | | Vertical Irregularities None None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  | | | |
| SE General Site Small mechanical room ignored. (seen in foreground) | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Foster Elementary School

Sweet Home SD 55

Linn_sch15C

| | | |
|-----------------|-----------------|-------|
| Building Type | County | |
| School | Linn | |
| Street | | |
| 5526 Poplar St. | | |
| City | State | Zip |
| Sweet Home | OR | 97386 |
| Latitude | Longitude | |
| 44.40974 | 122.66998 | |
| Tracking Code | Inspection Date | |
| RVS in 2006 | 7/3/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 4.8 | 0 | 0 | -0.2 | 0 | 0 | -1.2 | 0 | 3.4 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Foster Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 3.4 |

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Foster Elementary School

Linn_sch15C

| | | | |
|--|-------------------------------------|---|---------------------------|
| Enrollment 408 | Year Built (Field Verified) 1940 | Year Built (Alt. Source) 1940 | Est. Decade Built 1930 |
| Total Area (square ft) 39030 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities None None None | | Vertical Irregularities None None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  | | | |
| SE General Site | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Foster Elementary School

Sweet Home SD 55

Linn_sch15D

| | | |
|------------------------------|-----------------------------|--------------|
| Building Type School | County Linn | |
| Street 5526 Poplar St. | | |
| City Sweet Home | State OR | Zip 97386 |
| Latitude 44.40958 | Longitude 122.67001 | |
| Tracking Code RVS in 2006 | Inspection Date 7/3/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W1 | 5.2 | 0 | 0 | 0 | 0 | 0 | -0.6 | 0 | 4.6 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Foster Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W1 | 4.6 |

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Foster Elementary School

Linn_sch15D

| | | | |
|--|-------------------------------------|---|---------------------------|
| Enrollment 408 | Year Built (Field Verified) 1940 | Year Built (Alt. Source) 1940 | Est. Decade Built 1950 |
| Total Area (square ft) 39030 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities None None None | | Vertical Irregularities None None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  | | | |
| W General Site | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries