

# Scio High School

Scio SD 95

Linn\_sch23A

Building Type	County	
School	Linn	
Street		
38875 NW First Ave		
City	State	Zip
Scio	OR	97374
Latitude	Longitude	
44.70883	122.84843	
Tracking Code	Inspection Date	
RVS in 2006	6/30/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Tertiary		0	0	0	0	0	0	0	0	0

Scio High School

## Final RVS Score

Final Type	Final Score
RM1	-0.1

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

# Scio High School

Linn\_sch23A

Enrollment 245	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1950
Total Area (square ft) 92946	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards Unreinforced Chimneys None None		Poor Conditions None None None	
			
S Vertical Irregularity Primary reentrant corner		W Plan Irregularity Primary GYM - dual system (RM1 + W2) elevation step	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Scio High School

Scio SD 95

Linn\_sch23B

Building Type	County	
School	Linn	
Street		
38875 NW First Ave		
City	State	Zip
Scio	OR	97374
Latitude	Longitude	
44.70962	122.84813	
Tracking Code	Inspection Date	
RVS in 2006	6/30/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Scio High School

## Final RVS Score

Final Type	Final Score
RM1	2.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Scio High School

Linn\_sch23B

Enrollment 245	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1970
Total Area (square ft) 92946	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Primary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Scio High School

Scio SD 95

Linn\_sch23C

Building Type	County	
School	Linn	
Street		
38875 NW First Ave		
City	State	Zip
Scio	OR	97374
Latitude	Longitude	
44.7095	122.84854	
Tracking Code	Inspection Date	
RVS in 2006	6/30/2006	



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Scio High School

## Final RVS Score

Final Type	Final Score
RM1	1.9

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Scio High School

Linn\_sch23C

Enrollment 245	Year Built (Field Verified) 1956	Year Built (Alt. Source) 1956	Est. Decade Built 1990
Total Area (square ft) 92946	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Plan Irregularity Primary			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries