

Central Linn High School

Central Linn SD 552

Linn_sch27A

Building Type	County	
School	Linn	
Street		
32433 Hwy 228		
City	State	Zip
Halsey	OR	97348
Latitude	Longitude	
44.39016	123.08777	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary	URM	1.8	-1	-0.5	0	0	0	-0.6	0	-0.3

Central Linn High School

Final RVS Score

Final Type	Final Score
URM	-0.3

FEMA-154 Collapse Potential


Very High (100%)



OregonGeology

Central Linn High School

Linn_sch27A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built		
314	1959	1959	1950		
Total Area (square ft)	Number of Stories	Basement	Pounding Potential		
85811	1	No	No		
Plan Irregularities		Vertical Irregularities			
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes			
None		None			
None		None			
Falling Hazards		Poor Conditions			
Other: Smokestack		Cracks			
None		None			
None		None			
	E Primary Structural Type exterior walls are a single course of bricks- compare with image 3		E Primary Structural Type compare with image 2 (inside and outside of exterior wall)		W Other glu-lam arch that appears to cover the area of two basketball courts.
	W Plan Irregularity Primary		W Falling Hazard		W Other Buttress for glu-lam arch. This is one of the few that are exposed to the exterior. We suspect that the rest land into the main part of the school (n)
	NE Primary Structural Type Other than small masonry end (single course) this wall has wood columns and a lot of glass. Many similar places around school.		W Poor Condition		S General Site Arched area over gym is hidden by trees.



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries



S General Site



Central Linn High School

Central Linn SD 552

Linn_sch27B

Building Type	County
School	Linn
Street	
32433 Hwy 228	
City	State Zip
Halsey	OR 97348
Latitude	Longitude
44.39087	123.08707
Tracking Code	Inspection Date
RVS in 2006	7/7/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	0	0	0	0	-0.8	0	1
Secondary	S3	3.2	0	0	0	0	0	-0.6	0	2.6
Tertiary	RM1	2.8	-1	0	0	0	0	-0.6	0	1.2

Central Linn High School

Final RVS Score

Final Type	Final Score
W2	1

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Central Linn High School

Linn_sch27B

Enrollment 314	Year Built (Field Verified) 1959	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 85811	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions Cracks None None	
			
NW Primary Structural Type Brick, wood, and at the far right end light metal.		S Vertical Irregularity Primary	

Central Linn High School

Central Linn SD 552

Linn_sch27C

Building Type	County
School	Linn
Street	
32433 Hwy 228	
City	State Zip
Halsey	OR 97348
Latitude	Longitude
44.39041	123.08633
Tracking Code	Inspection Date
RVS in 2006	7/7/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	0	0	0	0	0	0	4.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Central Linn High School

Final RVS Score

Final Type	Final Score
W1	4.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Central Linn High School

Linn_sch27C

Enrollment 314	Year Built (Field Verified) 1959	Year Built (Alt. Source) 1959	Est. Decade Built 1970
Total Area (square ft) 85811	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries