

# Harrisburg High School

Harrisburg SD 7J

Linn\_sch29A

Building Type	County	
School	Linn	
Street		
400 S 9th St		
City	State	Zip
Harrisburg	OR	97446
Latitude	Longitude	
44.26979	123.16076	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg High School

## Final RVS Score

Final Type	Final Score
RM1	0.7

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Harrisburg High School

Linn\_sch29A

Enrollment 275	Year Built (Field Verified) 1973	Year Built (Alt. Source) 1973	Est. Decade Built 1970
Total Area (square ft) 69826	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: T shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Parapets: General None None		Poor Conditions None None None	
			
W Vertical Irregularity Primary shorter section on left	NE Plan Irregularity Primary	E General Site	

# Harrisburg High School

Harrisburg SD 7J

Linn\_sch29B

Building Type	County	
School	Linn	
Street		
400 S 9th St		
City	State	Zip
Harrisburg	OR	97446
Latitude	Longitude	
44.26896	123.16101	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg High School

## Final RVS Score

Final Type	Final Score
RM1	2.2

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Harrisburg High School

Linn\_sch29B

Enrollment 275	Year Built (Field Verified) 1973	Year Built (Alt. Source) 1973	Est. Decade Built 1990
Total Area (square ft) 69826	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	

# Harrisburg High School

Harrisburg SD 7J

Linn\_sch29C

Building Type School	County Linn	
Street 400 S 9th St		
City Harrisburg	State OR	Zip 97446
Latitude 44.26867	Longitude 123.16067	
Tracking Code RVS in 2006	Inspection Date 7/7/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg High School

### Final RVS Score

Final Type	Final Score
W2	0.5

### FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Harrisburg High School

Linn\_sch29C

Enrollment 275	Year Built (Field Verified) 1973	Year Built (Alt. Source) 1970	Est. Decade Built 1970
Total Area (square ft) 69826	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:T shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	

# Harrisburg High School

Harrisburg SD 7J

Linn\_sch29D

Building Type School	County Linn	
Street 400 S 9th St		
City Harrisburg	State OR	Zip 97446
Latitude 44.26856	Longitude 123.16025	
Tracking Code RVS in 2006	Inspection Date 7/7/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	0	-0.6	0	2.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg High School

## Final RVS Score

Final Type	Final Score
S3	2.1

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Harrisburg High School

Linn\_sch29D

Enrollment 275	Year Built (Field Verified) 1973	Year Built (Alt. Source) 1973	Est. Decade Built 1980
Total Area (square ft) 69826	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	

# Harrisburg High School

Harrisburg SD 7J

Linn\_sch29E

Building Type	County	
School	Linn	
Street		
400 S 9th St		
City	State	Zip
Harrisburg	OR	97446
Latitude	Longitude	
44.26915	123.16068	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Harrisburg High School

## Final RVS Score

Final Type	Final Score
RM1	2.2

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Harrisburg High School

Linn\_sch29E

Enrollment 275	Year Built (Field Verified) 1973	Year Built (Alt. Source) 1973	Est. Decade Built 1970
Total Area (square ft) 69826	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	