

# Central Linn Elementary School

Central Linn SD 552

Linn\_sch30A

Building Type School	County Linn	
Street 239 W 2nd St		
City Halsey	State OR	Zip 97348
Latitude 44.38725	Longitude 123.11111	
Tracking Code RVS in 2006	Inspection Date 7/7/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Central Linn Elementary School

## Final RVS Score

Final Type	Final Score
C2	0.7

## FEMA-154 Collapse Potential


High (>10%)



OregonGeology

# Central Linn Elementary School

Linn\_sch30A

Enrollment 351	Year Built (Field Verified) 1977	Year Built (Alt. Source) 1977	Est. Decade Built 1940
Total Area (square ft) 117390	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Smokestack		None	
None		None	
None		None	
			
E Primary Structural Type out of plane lateral system		NW Primary Structural Type	
			
		E Plan Irregularity Primary plan of building	

# Central Linn Elementary School

Linn\_sch30B

Central Linn SD 552

Building Type	County
School	Linn
Street	
239 W 2nd St	
City	State Zip
Halsey	OR 97348
Latitude	Longitude
44.38775	123.11135
Tracking Code	Inspection Date
RVS in 2006	7/7/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	PC1	2.6	0	-0.5	0	0	0	-0.6	0	1.5
Tertiary		0	0	0	0	0	0	0	0	0

Central Linn Elementary School

## Final RVS Score

Final Type	Final Score
RM1	0.7

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# Central Linn Elementary School

Linn\_sch30B

Enrollment 351	Year Built (Field Verified) 1977	Year Built (Alt. Source) 1977	Est. Decade Built 1970
Total Area (square ft) 117390	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent) Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None	
Falling Hazards None None None		Poor Conditions None None None	
			
NE Vertical Irregularity Primary	W Vertical Irregularity Primary	E General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries