


Cascades School

Lebanon Community SD 9

Linn_sch34A

Building Type	County	
School	Linn	
Street		
2163 7th St.		
City	State	Zip
Lebanon	OR	97355
Latitude	Longitude	
44.52468	122.91559	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	-0.5	0	0	0	-1.2	0	3.1
Secondary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Tertiary		0	0	0	0	0	0	0	0	0

Cascades School

Final RVS Score

Final Type	Final Score
RM1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Cascades School

Linn_sch34A

Enrollment 390	Year Built (Field Verified) 1953	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 38291	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Other: Smokestack None None		Poor Conditions None None None	
			
W Vertical Irregularity Primary	S General Site	S General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Cascades School

Lebanon Community SD 9

Linn_sch34B

Building Type	County	
School	Linn	
Street		
2163 7th St.		
City	State	Zip
Lebanon	OR	97355
Latitude	Longitude	
44.52551	122.91537	
Tracking Code	Inspection Date	
RVS in 2006	7/7/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	0	-1.2	0	0.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Cascades School

Final RVS Score

Final Type	Final Score
RM1	0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Cascades School

Linn_sch34B

Enrollment 390	Year Built (Field Verified) 1953	Year Built (Alt. Source) 1953	Est. Decade Built 1970
Total Area (square ft) 38291	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
E	Vertical Irregularity Primary	N	Vertical Irregularity Primary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries