

# Aiken Elementary School

Ontario SD 8C

Malh\_sch01A

Building Type	County
School	Malheur
Street	
1297 West Idaho St	
City	State Zip
Ontario	OR 97914
Latitude	Longitude
44.02905	116.98403
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	0	-1.2	0	3.6
Secondary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Tertiary		0	0	0	0	0	0	0	0	0

Aiken Elementary School

## Final RVS Score

Final Type	Final Score
RM1	2.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Aiken Elementary School

Malh\_sch01A

Enrollment 276	Year Built (Field Verified) 1957	Year Built (Alt. Source) 1957	Est. Decade Built 1960
Total Area (square ft) 22045	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: General Other: Brick Veneer None		Poor Conditions None None None	
			
E	Elevation View	S	Elevation View
			
S	Elevation View		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Aiken Elementary School

Ontario SD 8C

Malh\_sch01B

Building Type	County
School	Malheur
Street	
1297 West Idaho St	
City	State Zip
Ontario	OR 97914
Latitude	Longitude
44.02898	116.98308
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	0	-1.2	0	3.6
Secondary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Tertiary	C2	3.6	0	0	0	0	0	-1.2	0	2.4

Aiken Elementary School

## Final RVS Score

Final Type	Final Score
RM1	2.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Aiken Elementary School

Malh\_sch01B

Enrollment 276	Year Built (Field Verified) 1957	Year Built (Alt. Source) 1957	Est. Decade Built 1960
Total Area (square ft) 22045	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: General Other: Brick Veneer None		Poor Conditions None None None	
 W Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries