

May Roberts Elementary School

Ontario SD 8C

Malh_sch02A

Building Type	County
School	Malheur
Street	
590 NW 8th St	
City	State Zip
Ontario	OR 97914
Latitude	Longitude
44.0333	116.97102
Tracking Code	Inspection Date
RVS in 2006	6/29/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	W2	4.8	-3	-0.5	0	0	0	-1.2	0	0.1
Tertiary		0	0	0	0	0	0	0	0	0

May Roberts Elementary School

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

May Roberts Elementary School

Malh_sch02A

Enrollment 365	Year Built (Field Verified) 1970	Year Built (Alt. Source) 1970	Est. Decade Built 1960
Total Area (square ft) 33653	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
			
W Elevation View	N Primary Structural Type	N Elevation View gym	

May Roberts Elementary School

Ontario SD 8C

Malh_sch02B

Building Type	County
School	Malheur
Street	
590 NW 8th St	
City	State Zip
Ontario	OR 97914
Latitude	Longitude
44.03367	116.9714
Tracking Code	Inspection Date
RVS in 2006	6/29/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	5.2	0	0	0	0	0	-0.6	0	4.6
Secondary	S1	3.6	0	0	0	0	0	-1	0	2.6
Tertiary		0	0	0	0	0	0	0	0	0

May Roberts Elementary School

Final RVS Score

Final Type	Final Score
S1	2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

May Roberts Elementary School

Malh_sch02B

Enrollment 365	Year Built (Field Verified) 1970	Year Built (Alt. Source) 1970	Est. Decade Built 1950
Total Area (square ft) 33653	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
S Elevation View		W Seismic Upgrade	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries