

Pioneer Elementary School

Ontario SD 8C

Malh_sch03A

Building Type School	County Malheur	
Street 4744 Pioneer Rd		
City Ontario	State OR	Zip 97914
Latitude 44.11825	Longitude 116.9391	
Tracking Code RVS in 2006	Inspection Date 6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	-1.5	-0.5	-0.4	0	0	-0.8	0	0.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pioneer Elementary School

Final RVS Score

Final Type	Final Score
URM	0.2

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Pioneer Elementary School

Malh_sch03A

Enrollment 139	Year Built (Field Verified) 1964	Year Built (Alt. Source) 1964	Est. Decade Built 1930
Total Area (square ft) 12860	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 W Elevation View		 N Elevation View	
		 E Elevation View	

Pioneer Elementary School

Ontario SD 8C

Malh_sch03B

Building Type School	County Malheur	
Street 4744 Pioneer Rd		
City Ontario	State OR	Zip 97914
Latitude 44.11791	Longitude 116.93912	
Tracking Code RVS in 2006	Inspection Date 6/30/2006	



Seismicity Zone: Moderate										Pioneer Elementary School		
FEMA 154 Rapid Visual Screening Score Card										Final RVS Score		
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score	Final Type	Final Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1	RM1	-0.1
Secondary		0	0	0	0	0	0	0	0	0		
Tertiary		0	0	0	0	0	0	0	0	0		Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pioneer Elementary School

Malh_sch03B

Enrollment 139	Year Built (Field Verified) 1964	Year Built (Alt. Source) 1960	Est. Decade Built 1960
Total Area (square ft) 12860	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: H Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 SW Elevation View		 S Primary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Pioneer Elementary School

Ontario SD 8C

Malh_sch03C

Building Type School	County Malheur	
Street 4744 Pioneer Rd		
City Ontario	State OR	Zip 97914
Latitude 44.1183	Longitude 116.93864	
Tracking Code RVS in 2006	Inspection Date 6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Pioneer Elementary School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Pioneer Elementary School

Malh_sch03C

Enrollment 139	Year Built (Field Verified) 1964	Year Built (Alt. Source) 1964	Est. Decade Built 1960
Total Area (square ft) 12860	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
			
N Elevation View		N Primary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries