

Ontario Middle School

Malh_sch04A

Ontario SD 8C

Building Type		County	
School		Malheur	
Street			
573 SW 2nd			
City	State	Zip	
Ontario	OR	97914	
Latitude		Longitude	
44.02643		116.97048	
Tracking Code		Inspection Date	
RVS in 2006		6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ontario Middle School

Final RVS Score

Final Type

Final Score

RM1

2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
698		1939	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
148000	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
None	None
None	None



Ontario Middle School

Malh_sch04B

Ontario SD 8C

Building Type		County	
School		Malheur	
Street			
573 SW 2nd			
City	State	Zip	
Ontario	OR	97914	
Latitude		Longitude	
44.02627		116.97005	
Tracking Code		Inspection Date	
RVS in 2006		6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	0	0	0	0	-1.2	0	0.4
Secondary	RM1	3.6	-2	0	0	0	0	-1.2	0	0.4
Tertiary		0	0	0	0	0	0	0	0	0

Ontario Middle School

Final RVS Score

Final Type

Final Score

C2

0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
698		1939	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Ontario Middle School

Malh_sch04C

Ontario SD 8C

Building Type		County	
School		Malheur	
Street			
573 SW 2nd			
City	State	Zip	
Ontario	OR	97914	
Latitude		Longitude	
44.02612		116.96944	
Tracking Code		Inspection Date	
RVS in 2006		6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	0	-0.5	-0.4	0	0	-0.8	0	1.7
Secondary	C2	3.6	0	-0.5	-0.4	0	0	-1.2	0	1.5
Tertiary		0	0	0	0	0	0	0	0	0

Ontario Middle School

Final RVS Score

Final Type

Final Score

C2

1.5

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
698	1939	1939	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Out of Plane Lateral-Force-Resistance Elements	None
Reentrant Corners: L Shaped	None
None	None

Falling Hazards	Poor Conditions
Parapets: Unreinforced Across Front of Building	None
None	None
None	None



W Elevation View



S Elevation View



Ontario Middle School

Malh_sch04D

Ontario SD 8C

Building Type		County	
School		Malheur	
Street			
573 SW 2nd			
City	State	Zip	
Ontario	OR	97914	
Latitude		Longitude	
44.02573		116.97045	
Tracking Code		Inspection Date	
RVS in 2006		6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	0	0	0	0	-1.2	0	0.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ontario Middle School

Final RVS Score

Final Type

Final Score

RM1

0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
698		1939	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	Steps in Elevation View: Single Change
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



Ontario Middle School

Malh_sch04E

Ontario SD 8C

Building Type		County	
School		Malheur	
Street			
573 SW 2nd			
City	State	Zip	
Ontario	OR	97914	
Latitude		Longitude	
44.02553		116.96959	
Tracking Code		Inspection Date	
RVS in 2006		6/30/2006	


Seismicity Zone: Moderate											Ontario Middle School	
FEMA 154 Rapid Visual Screening Score Card											Final RVS Score	
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score	Final Type	Final Score
Primary	URM	3.4	0	-0.5	-0.4	0	0	-0.8	0	1.7	C2	1.5
Secondary	C2	3.6	0	-0.5	-0.4	0	0	-1.2	0	1.5	FEMA-154 Collapse Potential	
Tertiary		0	0	0	0	0	0	0	0	0	Moderate (>1%)	



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
698	1939	1939	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: U shaped	None
None	None
None	None

Falling Hazards	Poor Conditions
Parapets: Unreinforced Across Front of Building	None
None	None
None	None



Ontario Middle School

Malh_sch04F

Ontario SD 8C

Building Type		County	
School		Malheur	
Street			
573 SW 1st			
City	State	Zip	
Ontario	OR	97914	
Latitude		Longitude	
44.0252		116.96972	
Tracking Code		Inspection Date	
RVS in 2006		6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	3.4	0	0	-0.4	0	0	-0.8	0	2.2
Secondary	C2	3.6	0	0	-0.4	0	0	-1.2	0	2
Tertiary		0	0	0	0	0	0	0	0	0

Ontario Middle School

Final RVS Score

Final Type

Final Score

C2

2

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
698	1939	1939	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
None	None
None	None
None	None

Falling Hazards	Poor Conditions
Parapets: Unreinforced Across Front of Building	None
None	None
None	None



W Elevation View

