

Ontario High School

Ontario SD 8C

Malh_sch05A

Building Type	County
School	Malheur
Street	
1115 West Idaho Ave	
City	State Zip
Ontario	OR 97914
Latitude	Longitude
44.02962	116.97773
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ontario High School

Final RVS Score

Final Type

C2

Final Score

-0.1

FEMA-154 Collapse Potential

Very High (100%)



Ontario High School

Malh_sch05A

Enrollment 784	Year Built (Field Verified) 1980	Year Built (Alt. Source) 1980	Est. Decade Built 1950
Total Area (square ft) 87681	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: E Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards None None None		Poor Conditions None None None	
 W Primary Structural Type			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Ontario High School

Ontario SD 8C

Malh_sch05B

Building Type	County
School	Malheur
Street	
1115 West Idaho Ave	
City	State Zip
Ontario	OR 97914
Latitude	Longitude
44.02988	116.97871
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ontario High School

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Ontario High School

Malh_sch05B

Enrollment 784	Year Built (Field Verified) 1980	Year Built (Alt. Source) 1980	Est. Decade Built 1970
Total Area (square ft) 87681	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 S Elevation View		 W Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Ontario High School

Ontario SD 8C

Malh_sch05C

Building Type	County
School	Malheur
Street	
1115 West Idaho Ave	
City	State Zip
Ontario	OR 97914
Latitude	Longitude
44.02975	116.97844
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Ontario High School

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Ontario High School

Malh_sch05C

Enrollment 784	Year Built (Field Verified) 1980	Year Built (Alt. Source) 1980	Est. Decade Built 1970
Total Area (square ft) 87681	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards Other: Smokestack None None		Poor Conditions None None None	
 W Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries