

Vale Elementary School

Vale SD 84

Malh_sch06A

| | | |
|------------------------------|------------------------------|--------------|
| Building Type School | County Malheur | |
| Street 403 E St W | | |
| City Vale | State OR | Zip 97918 |
| Latitude 43.97879 | Longitude 117.24208 | |
| Tracking Code RVS in 2006 | Inspection Date 6/30/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 4.8 | 0 | 0 | 0 | 1.6 | 0 | -1.2 | 0 | 5.2 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Vale Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 5.2 |

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Vale Elementary School

Malh_sch06A

| | | | |
|---|-------------------------------------|---|---------------------------|
| Enrollment 420 | Year Built (Field Verified) 1954 | Year Built (Alt. Source) 1954 | Est. Decade Built 2000 |
| Total Area (square ft) 52900 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities None None None | | Vertical Irregularities None None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |

Vale Elementary School

Vale SD 84

Malh_sch06B

| | |
|---------------|-----------------|
| Building Type | County |
| School | Malheur |
| Street | |
| 403 E St W | |
| City | State Zip |
| Vale | OR 97918 |
| Latitude | Longitude |
| 43.97857 | 117.24301 |
| Tracking Code | Inspection Date |
| RVS in 2006 | 6/30/2006 |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 4.8 | -3 | -0.5 | 0 | 0 | 0 | -1.2 | 0 | 0.1 |
| Secondary | C2 | 3.6 | -2 | -0.5 | 0 | 0 | 0 | -1.2 | 0 | -0.1 |
| Tertiary | URM | 3.4 | -1.5 | -0.5 | 0 | 0 | 0 | -0.8 | 0 | 0.6 |

Vale Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2 | -0.1 |

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Vale Elementary School

Malh_sch06B

| | | | |
|---|-------------------------------------|---|---------------------------|
| Enrollment 420 | Year Built (Field Verified) 1954 | Year Built (Alt. Source) 1950 | Est. Decade Built 1950 |
| Total Area (square ft) | Number of Stories 1 | Basement | Pounding Potential Yes |
| Plan Irregularities Reentrant Corners: U shaped Reentrant Corners: L Shaped (Adjacent Build/Entity) None | | Vertical Irregularities Steps in Elevation View: Single Change None None | |
| Falling Hazards Other: Smokestack Other: General Other: Brick Veneer | | Poor Conditions None None None | |
|  | |  | |
| S Primary Structural Type | | S Primary Structural Type | |
| | | S Primary Structural Type urn wall | |
|  | | | |
| S Falling Hazard | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Vale Elementary School

Vale SD 84

Malh_sch06C

| | | |
|------------------------------|------------------------------|--------------|
| Building Type School | County Malheur | |
| Street 403 E St W | | |
| City Vale | State OR | Zip 97918 |
| Latitude 43.97869 | Longitude 117.24384 | |
| Tracking Code RVS in 2006 | Inspection Date 6/30/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | RM1 | 3.6 | 0 | -0.5 | 0 | 2 | 0 | -1.2 | 0 | 3.9 |
| Secondary | W2 | 4.8 | 0 | -0.5 | 0 | 1.6 | 0 | -1.2 | 0 | 4.7 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Vale Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1 | 3.9 |

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Vale Elementary School

Malh_sch06C

| | | | |
|--|-------------------------------------|---|---------------------------|
| Enrollment 420 | Year Built (Field Verified) 1954 | Year Built (Alt. Source) 1954 | Est. Decade Built 2000 |
| Total Area (square ft) | Number of Stories 1 | Basement | Pounding Potential Yes |
| Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None | | Vertical Irregularities None None None | |
| Falling Hazards Other: Brick Veneer None None | | Poor Conditions None None None | |
|  S Elevation View | |  S Elevation View | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Vale Elementary School

Vale SD 84

Malh_sch06D

| | | |
|------------------------------|------------------------------|--------------|
| Building Type School | County Malheur | |
| Street 403 E St W | | |
| City Vale | State OR | Zip 97918 |
| Latitude 43.97807 | Longitude 117.24278 | |
| Tracking Code RVS in 2006 | Inspection Date 6/30/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | C2 | 3.6 | 0 | -0.5 | 0 | 0 | 0 | -1.2 | 0 | 1.9 |
| Secondary | W2 | 4.8 | 0 | -0.5 | 0 | 0 | 0 | -1.2 | 0 | 3.1 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Vale Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2 | 1.9 |

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Vale Elementary School

Malh_sch06D

| | | | |
|--|-------------------------------------|---|---------------------------|
| Enrollment 420 | Year Built (Field Verified) 1954 | Year Built (Alt. Source) 1954 | Est. Decade Built 1950 |
| Total Area (square ft) | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities Reentrant Corners: L Shaped None None | | Vertical Irregularities None None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  N Elevation View | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Vale Elementary School

Vale SD 84

Malh_sch06E

| | | |
|------------------------------|------------------------------|--------------|
| Building Type School | County Malheur | |
| Street 403 E St W | | |
| City Vale | State OR | Zip 97918 |
| Latitude 43.97874 | Longitude 117.24358 | |
| Tracking Code RVS in 2006 | Inspection Date 6/30/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | C2 | 3.6 | -2 | -0.5 | 0 | 0 | 0 | -1.2 | 0 | -0.1 |
| Secondary | W2 | 4.8 | -3 | -0.5 | 0 | 0 | 0 | -1.2 | 0 | 0.1 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Vale Elementary School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2 | -0.1 |

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Vale Elementary School

Malh_sch06E

| | | | |
|---|-------------------------------------|--|---------------------------|
| Enrollment 420 | Year Built (Field Verified) 1954 | Year Built (Alt. Source) 1954 | Est. Decade Built 1970 |
| Total Area (square ft) | Number of Stories 1 | Basement | Pounding Potential Yes |
| Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None | | Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |