

Nyssa Elementary School

Nyssa SD 26

Malh_sch07A

Building Type		County	
School		Malheur	
Street			
809 Bower Ave			
City	State	Zip	
Nyssa	OR	97913	
Latitude		Longitude	
43.87681		117.003	
Tracking Code		Inspection Date	
New Building		7/27/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Nyssa Elementary School

Final RVS Score

Final Type

Final Score

--	--

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
566	1998	1998	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
66044	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions