

Nyssa High School

Nyssa SD 26

Malh_sch09A

Building Type School	County Malheur	
Street 824 Adrian Blvd		
City Nyssa	State OR	Zip 97913
Latitude 43.87456	Longitude 117.00564	
Tracking Code RVS in 2006	Inspection Date 6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Secondary	C2	3.6	0	-0.5	0	0	0	-1.2	0	1.9
Tertiary		0	0	0	0	0	0	0	0	0

Nyssa High School

Final RVS Score

Final Type	Final Score
RM1	1.9

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Nyssa High School

Malh_sch09A

Enrollment 318	Year Built (Field Verified) 1974	Year Built (Alt. Source) 1974	Est. Decade Built 1970
Total Area (square ft) 38058	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: U shaped None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 N Elevation View		 E Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Nyssa High School

Nyssa SD 26

Malh_sch09B

Building Type School	County Malheur	
Street 824 Adrian Blvd		
City Nyssa	State OR	Zip 97913
Latitude 43.87495	Longitude 117.00469	
Tracking Code RVS in 2006	Inspection Date 6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary	C2	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Nyssa High School

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Nyssa High School

Malh_sch09B

Enrollment 318	Year Built (Field Verified) 1974	Year Built (Alt. Source) 1974	Est. Decade Built 1970
Total Area (square ft) 38058	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards None None None		Poor Conditions None None None	
 S Primary Structural Type inside		 S Primary Structural Type inside aud	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Nyssa High School

Nyssa SD 26

Malh_sch09C

Building Type School	County Malheur	
Street 824 Adrian Blvd		
City Nyssa	State OR	Zip 97913
Latitude 43.87551	Longitude 117.00412	
Tracking Code RVS in 2006	Inspection Date 6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Secondary	C2	3.6	0	0	0	0	0	-1.2	0	2.4
Tertiary		0	0	0	0	0	0	0	0	0

Nyssa High School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Nyssa High School

Malh_sch09C

Enrollment 318	Year Built (Field Verified) 1974	Year Built (Alt. Source) 1974	Est. Decade Built 1970
Total Area (square ft) 38058	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries