

Vale High School

Vale SD 84

Malh_sch11A

Building Type School	County Malheur	
Street 505 Viking Dr		
City Vale	State OR	Zip 97918
Latitude 43.97859	Longitude 117.25237	
Tracking Code RVS in 2006	Inspection Date 6/30/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	0	0	0	0	-1.2	0	0.6
Secondary	RM1	3.6	-2	0	0	0	0	-1.2	0	0.4
Tertiary		0	0	0	0	0	0	0	0	0

Vale High School

Final RVS Score

Final Type	Final Score
RM1	0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Vale High School

Malh_sch11A

Enrollment 335	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1950
Total Area (square ft) 71503	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Parapets: General Other: Brick Veneer None		Poor Conditions None None None	
			
S Primary Structural Type inside gym wood structure		S Elevation View	
		S Elevation View	
		S Elevation View	
			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Vale High School

Vale SD 84

Malh_sch11B

Building Type	County
School	Malheur
Street	
505 Viking Dr	
City	State Zip
Vale	OR 97918
Latitude	Longitude
43.9787	117.25273
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	-1.2	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Vale High School

Final RVS Score

Final Type	Final Score
RM1	-0.1

FEMA-154 Collapse Potential

Very High (100%)



Enrollment 335	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1960
Total Area (square ft) 71503	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: L Shaped None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards Other: Smokestack None None		Poor Conditions None None None	

Vale High School

Vale SD 84

Malh_sch11C

Building Type	County
School	Malheur
Street	
505 Viking Dr	
City	State Zip
Vale	OR 97918
Latitude	Longitude
43.97913	117.25259
Tracking Code	Inspection Date
RVS in 2006	6/30/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	0	0	1.6	0	-1.2	0	4
Secondary	RM1	3.6	0	0	0	0	0	-1.2	0	2.4
Tertiary		0	0	0	0	0	0	0	0	0

Vale High School

Final RVS Score

Final Type	Final Score
RM1	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Vale High School

Malh_sch11C

Enrollment 335	Year Built (Field Verified) 1958	Year Built (Alt. Source) 1958	Est. Decade Built 1990
Total Area (square ft) 71503	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities Internal Discontinuous Diaphram (large internal opening) None None	
Falling Hazards None None None		Poor Conditions None None None	
 E Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries