

Technical Skills (#005)

Mari_coc09A

Chemeketa CC

| | | | |
|----------------------|-------|-----------------|--|
| Building Type | | County | |
| Community_College | | Marion | |
| Street | | | |
| 4000 Lancaster Dr Ne | | | |
| City | State | Zip | |
| Salem | OR | 97309 | |
| Latitude | | Longitude | |
| 44.97908 | | 122.97672 | |
| Tracking Code | | Inspection Date | |
| Miller 2004-05 | | 6/24/2004 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | RM1 | 2.8 | -1 | -0.5 | 0 | 0 | 0 | -0.6 | 0 | 0.7 |
| Secondary | RM2 | 2.8 | -1 | -0.5 | 0 | 0 | 0 | -0.6 | 0 | 0.7 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Technical Skills (#005)

Final RVS Score

Final Type


Final Score

RM1

0.7

FEMA-154 Collapse Potential

High (>10%)



Salem Campus Map Legend

- | | |
|--|--|
| 1. Bookstore and staff offices | 26. Classrooms A-B |
| 2. Counseling & Career Services, Business Office, Financial Aid, Human Resources, President's Office, College Advancement, Purchasing, Enrollment Services, Student Records, Tutoring, Food Court, Disability Services, Student Life and Academic Support Services Office, Public Safety, College Access Programs, C-Store, College Support Services | 27. Classrooms A-B |
| 3. General classrooms, Math lab, Theater 316 (Movie Theater) | 28. Classrooms A-F |
| 4. Technical Skills classrooms, Crossroads | 29. Hospitality program offices, staff offices and classroom |
| | 30. Classrooms |
| | 31. Classroom |
| | 32. Classrooms A-F |
| | 33. Mailing, Receiving, C Copy Plus |
| | 34. Food Service Kitchen & Meeting Rooms |
| | 35. Writing Center and classrooms |
| | 36. Classrooms |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Technical Skills (#005)

Mari_coc09A

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | 1975 | 1975 | 1970 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 29451 | 2 | No | No |

| | |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| None | None |
| | |
| | |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| None | |
| None | |
| None | |



S General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries