

Building Type Community_College	County Marion	
Street 120 East Lincoln Street		
City Woodburn	State OR	Zip 97071
Latitude 45.14308	Longitude 122.85461	
Tracking Code New Building	Inspection Date 3/1/2007	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Branch - Woodburn Center

## Final RVS Score

Final Type	Final Score
<input type="text"/>	<input type="text"/>

## FEMA-154 Collapse Potential

 Low (<1%)

No  
Planview  
Available



OregonGeology

# Branch - Woodburn Center

Mari\_coc15A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	2003	2003	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
28000		No	No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	