

Silverton RFPD Abiqua Station #3

Mari_fir02A

Silverton RFPD

Building Type	County	
Fire - RFPD	Marion	
Street		
17447 N Abiqua Rd		
City	State	Zip
Silverton	OR	97381
Latitude	Longitude	
45.02149	122.70365	
Tracking Code	Inspection Date	
RVS in 2006	8/2/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	-0.4	0	0	2.9
Secondary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Tertiary		0	0	0	0	0	0	0	0	0

Silverton RFPD Abiqua Station #3

Final RVS Score

Final Type	Final Score
S3	2.3

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Silverton RFPD Abiqua Station #3

Mari_fir02A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Elevation View		SW Building Name	
		NW Elevation View	
			
SE Primary Structural Type		S Secondary Structural Type	
		SW Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries