

# Silverton RFPD

Silverton RFPD

Mari\_fir05A

|                                  |                             |              |
|----------------------------------|-----------------------------|--------------|
| Building Type<br>Fire - RFPD     | County<br>Marion            |              |
| Street<br>4724 Crooked Finger Rd |                             |              |
| City<br>Scotts Mills             | State<br>OR                 | Zip<br>97375 |
| Latitude<br>44.99289             | Longitude<br>122.62079      |              |
| Tracking Code<br>RVS in 2006     | Inspection Date<br>8/2/2006 |              |



Seismicity Zone: High

| FEMA 154 Rapid Visual Screening Score Card |      |             |            |            |          |            |        |        |        |           |
|--|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
|  | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
| Primary                                    | W1   | 4.4         | 0          | -0.5       | 0        | 0          | 0      | 0      | 0      | 3.9       |
| Secondary                                  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary                                   |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Silverton RFPD

| Final RVS Score |             |
|-----------------|-------------|
| Final Type      | Final Score |
| W1              | 3.9         |

FEMA-154 Collapse Potential

|           |
|-----------|
| Low (<1%) |
|-----------|



|  |                             |  |                    |
|--|-----------------------------|--|--------------------|
| Enrollment   | Year Built (Field Verified) | Year Built (Alt. Source)   | Est. Decade Built  |
|  |                             |  | 1950               |
| Total Area (square ft)   | Number of Stories           | Basement   | Pounding Potential |
|  | 1                           | No   | No                 |
| Plan Irregularities  |                             | Vertical Irregularities  |                    |
| Torsion: Eccentric Stiffness   |                             | None   |                    |
| None   |                             | None   |                    |
| None   |                             | None   |                    |
| Falling Hazards  |                             | Poor Conditions  |                    |
| None   |                             | None   |                    |
| None   |                             | None   |                    |
| None   |                             | None   |                    |
|  |                             |   |                    |
| SW Elevation View  |                             | NW Elevation View  |                    |
|  |                             |  |                    |
|  |                             | E Primary Structural Type<br>wood  |                    |

