

Aurora RFPD

Aurora RFPD

Mari_fir06A

Building Type	County	
Fire - RFPD	Marion	
Street		
20909 Feller St		
City	State	Zip
Donald	OR	97020
Latitude	Longitude	
45.2218	122.84108	
Tracking Code	Inspection Date	
RVS in 2006	7/26/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary	C1	2.5	0	-0.5	0	0	0	-0.6	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0

Aurora RFPD

Final RVS Score

Final Type	Final Score
C1	1.4

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built		
			1960		
Total Area (square ft)	Number of Stories	Basement	Pounding Potential		
	1	No	No		
Plan Irregularities		Vertical Irregularities			
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change			
Torsion: Eccentric Stiffness		None			
None		None			
Falling Hazards		Poor Conditions			
Other: Ornamental Hazard Over Exit		None			
None		None			
None		None			
	SW General Site		NW Plan Irregularity Primary		SW Falling Hazard
	W Vertical Irregularity Primary		NW General Site		E Building Name
	E Primary Structural Type		E Secondary Structural Type		
<p>columns on these bays are cast in place concrete, along with the beam above the doors.</p> <p>The rest is RM1</p>		<p>columns on left bay are cast in place concrete, the beam above the doors is also Concrete</p>			

