

Silverton RFPD

Mari_fir09A

Silverton RFPD

Building Type Fire - RFPD	County Marion	
Street 819 Rail Way Ave NE		
City Silverton	State OR	Zip 97381
Latitude 45.00497	Longitude 122.79626	
Tracking Code New Building	Inspection Date 8/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	0	0	0	2.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Silverton RFPD

Final RVS Score

Final Type	Final Score
S3	2.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1998	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2574	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: T shaped		Internal Discontinuous Diaphram (large internal opening)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N General Site MUSEUM NOT SCREENED		NW Plan Irregularity Primary	
			
SW Elevation View		W Primary Structural Type	
			
SE Elevation View		SW General Site PRACTICE TOWER	



Silverton RFPD

Mari_fir09B

Silverton RFPD

Building Type Fire - RFPD	County Marion	
Street 819 Rail Way Ave NE		
City Silverton	State OR	Zip 97381
Latitude 45.00383	Longitude 122.79592	
Tracking Code New Building	Inspection Date 8/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	0	0	0	3.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Silverton RFPD

Final RVS Score

Final Type	Final Score
S3	3.2

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1998	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2574	1	No	Yes
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Elevation View	N Primary Structural Type	NE Elevation View	



Silverton RFPD

Building Type Fire - RFPD	County Marion	
Street 819 Rail Way Ave NE		
City Silverton	State OR	Zip 97381
Latitude 45.00399	Longitude 122.79543	
Tracking Code New Building	Inspection Date 8/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	0	0	0	3.2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Silverton RFPD

Final RVS Score

Final Type	Final Score
S3	3.2

FEMA-154 Collapse Potential

Low (<1%)



Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1998	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
2574	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Elevation View			

