

Salem Fire Dept - Station 06

City of Salem

Mari_fir10A

Building Type	County
Fire - City	Marion
Street	
2740 25th St SE	
City	State Zip
Salem	OR 97301
Latitude	Longitude
44.91371	123.00928
Tracking Code	Inspection Date
To be Retrofit	8/7/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	0	0	0	0	-0.4	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Salem Fire Dept - Station 06

Final RVS Score

Final Type	Final Score
C2	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Salem Fire Dept - Station 06

Mari_fir10A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
Lateral-Force-Resistance in One Direction Only		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W Vertical Irregularity Secondary		W Plan Irregularity Secondary	
		NW Plan Irregularity Primary SMALL WOOD FRAMED ADDITION ON N SIDE OF STATION	
			
SW Elevation View		NE Elevation View	
		SE Elevation View	
			
NE Elevation View		N Elevation View BLDG NOT SURVEYED	
		W General Site BLDG NOT SURVEYED	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries