

# Stayton RFPD

Stayton RFPD

Mari\_fir14A

|                              |                              |              |
|------------------------------|------------------------------|--------------|
| Building Type<br>Fire - RFPD | County<br>Marion             |              |
| Street<br>1988 W Ida St      |                              |              |
| City<br>Stayton              | State<br>OR                  | Zip<br>97383 |
| Latitude<br>44.79685         | Longitude<br>122.81403       |              |
| Tracking Code<br>RVS in 2006 | Inspection Date<br>7/18/2006 |              |



Seismicity Zone: Moderate

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 3.6         | -2         | -0.5       | 0        | 0          | 0      | -1.2   | 0      | -0.1      |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Stayton RFPD

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1        | -0.1        |

## FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

|  |                                   |   |                               |
|--|-----------------------------------|---|-------------------------------|
| Enrollment   | Year Built (Field Verified)       | Year Built (Alt. Source)  | Est. Decade Built             |
|  | 1989                              | 1989  | 1980                          |
| Total Area (square ft)   | Number of Stories                 | Basement  | Pounding Potential            |
| 15589  | 2                                 | No  | No                            |
| Plan Irregularities  |                                   | Vertical Irregularities   |                               |
| Reentrant Corners: Other   |                                   | Steps in Elevation View: 2 to 3 Changes   |                               |
| None   |                                   | None  |                               |
| None   |                                   | None  |                               |
| Falling Hazards  |                                   | Poor Conditions   |                               |
| None   |                                   | None  |                               |
| None   |                                   | None  |                               |
| None   |                                   | None  |                               |
|    |                                   |     |                               |
| W  | Field Verified Year Built<br>1989 | SW  | General Site                  |
|   |                                   |    |                               |
| N  | Primary Structural Type           | NE  | Vertical Irregularity Primary |
|  |                                   |  |                               |
| SW   | Plan Irregularity Primary         | SW  | General Site                  |
|   |                                   |    |                               |
| SW   | Plan Irregularity Secondary       | NW  | General Site                  |

