

Hubbard RFPD

Mari_fir15A

Hubbard RFPD

Building Type Fire - RFPD	County Marion	
Street 3161 2nd St		
City Hubbard	State OR	Zip 97032
Latitude 45.17974	Longitude 122.80952	
Tracking Code RVS in 2006	Inspection Date 7/26/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Hubbard RFPD

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1975	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
9254	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
 SE Primary Structural Type		 NE General Site	
		 NW General Site	



Hubbard RFPD

Building Type	County	
Fire - RFPD	Marion	
Street		
3161 2nd St		
City	State	Zip
Hubbard	OR	97032
Latitude	Longitude	
45.17995	122.80915	
Tracking Code	Inspection Date	
RVS in 2006	7/26/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	0	-0.6	0	1.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Hubbard RFPD

Final RVS Score

Final Type	Final Score
PC1	1.5

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1975	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: Single Change	
Reentrant Corners: L Shaped (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Torsion: Eccentric Stiffness		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
	SW General Site		SW General Site
	N Primary Structural Type welded joint at base of tilt up.		NE General Site
	SE Building Name		SW Primary Structural Type caulked joint

