

Salem Fire Dept - Station 07

City of Salem

Mari_fir18A

Building Type	County	
Fire - City	Marion	
Street		
4730 Liberty Rd SE		
City	State	Zip
Salem	OR	97306
Latitude	Longitude	
44.89002	123.06006	
Tracking Code	Inspection Date	
To be Re-built	8/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Salem Fire Dept - Station 07

Final RVS Score

Final Type	Final Score
RM1	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Salem Fire Dept - Station 07

Mari_fir18A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Lateral-Force-Resistance in One Direction Only		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Plan Irregularity Secondary	SW	Vertical Irregularity Primary
			
NW	Elevation View	SE	Vertical Irregularity Secondary
			
E	Plan Irregularity Secondary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries