

# Stayton RFPD

Stayton RFPD

Mari\_fir23A

Building Type Fire - RFPD	County Marion	
Street 5898 Stayton Rd		
City Turner	State OR	Zip 97392
Latitude 44.75032	Longitude 122.94015	
Tracking Code RVS in 2006	Inspection Date 8/3/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Secondary	W2	3.8	0	-0.5	0	2.4	-0.4	0	0	5.3
Tertiary		0	0	0	0	0	0	0	0	0

Stayton RFPD

## Final RVS Score

Final Type	Final Score
S3	2.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NW General Site		SW Elevation View	
		E Elevation View	
		NE Elevation View	

