

# Woodburn RFPD Waconda Station Office

Woodburn RFPD

Mari\_fir27A

Building Type Fire - RFPD	County Marion	
Street 11484 River Rd		
City Gervais	State OR	Zip 97026
Latitude 45.08572	Longitude 122.97599	
Tracking Code RVS in 2006	Inspection Date 7/28/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	0	0	0	-0.6	0	2.2
Secondary	S3	3.2	0	0	0	0	0	-0.6	0	2.6
Tertiary	W1	4.4	0	0	0	0	0	0	0	4.4

Woodburn RFPD Waconda Station Office

## Final RVS Score

Final Type	Final Score
RM1	2.2

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Woodburn RFPD Waconda Station Office

Mari\_fir27A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E Primary Structural Type		SE Elevation View	
			
		SW Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Woodburn RFPD Waconda Station Garage

Woodburn RFPD

Mari\_fir27B

Building Type Fire - RFPD	County Marion	
Street 11484 River Rd		
City Gervais	State OR	Zip 97026
Latitude 45.08585	Longitude 122.97592	
Tracking Code RVS in 2006	Inspection Date 7/28/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	0	-0.8	0	2.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Woodburn RFPD Waconda Station Garage

## Final RVS Score

Final Type	Final Score
W2	2.5

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Woodburn RFPD Waconda Station Garage

Mari\_fir27B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Lateral-Force-Resistance in One Direction Only		None	
Lateral-Force-Resistance		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
	NE Elevation View		E General Site
<p>W Primary Structural Type THIS BUILDING IS A POLE BARN - STRUCTURE TYPE IS ALSO DESCRIBED ON WEBSITE</p>			