

Monitor RFPD #58

Mari_fir41A

Monitor RFPD

Building Type Fire - RFPD	County Marion	
Street 15240 Woodburn Monitor Rd		
City Woodburn	State OR	Zip 97071
Latitude 45.10118	Longitude 122.74883	
Tracking Code New Building	Inspection Date 7/27/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	0	0	0	-0.4	0	0	2.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Monitor RFPD #58

Final RVS Score

Final Type	Final Score
S3	2.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Monitor RFPD #58

Mari_fir41A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1994	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
8700	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		Steps in Elevation View: 2 to 3 Changes	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE General Site		NW Building Name	
		NE General Site	
			
N Primary Structural Type S3		NW Plan Irregularity Primary	
		SE General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries