

Mt Angel Fire Dept

City of Mt Angel

Mari_fir42A

Building Type	County	
Fire - City	Marion	
Street		
300 Monroe St		
City	State	Zip
Mount Angel	OR	97362
Latitude	Longitude	
45.06998	122.79977	
Tracking Code	Inspection Date	
RVS in 2006	8/1/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	2.4	0	0	0	3.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Mt Angel Fire Dept

Final RVS Score

Final Type	Final Score
W1	3.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Mt Angel Fire Dept

Mari_fir42A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE Elevation View		SE Elevation View	
			
SW Plan Irregularity Primary		SE Primary Structural Type	
			
E Building Name			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Mt Angel Fire Dept

City of Mt Angel

Mari_fir42B

Building Type	County	
Fire - City	Marion	
Street		
300 Monroe St		
City	State	Zip
Mount Angel	OR	97362
Latitude	Longitude	
45.06998	122.80006	
Tracking Code	Inspection Date	
RVS in 2006	8/1/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Mt Angel Fire Dept

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Mt Angel Fire Dept

Mari_fir42B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Lateral-Force-Resistance in One Direction Only		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Primary Structural Type		NW Elevation View	
		NW Elevation View	
			
NW Plan Irregularity Tertiary		N Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries