

Silverton Hospital

NFP - Silverton

Mari_hos01A

Building Type Hospital	County Marion	
Street 342 Fairview St		
City Silverton	State OR	Zip 97381
Latitude 45.00431	Longitude 122.78983	
Tracking Code New Building	Inspection Date 8/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S2	3	-1.5	-0.5	0	1.4	0	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Silverton Hospital

Final RVS Score

Final Type	Final Score
S2	2.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Silverton Hospital

Mari_hos01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1995	2000
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
Reentrant Corners: Other (Adjacent Build/Entity)		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
E Field Verified Year Built		SE Elevation View EFIS WALLS ON NEWER PART	
		E General Site CONN TO OLD	
		W Elevation View	
		W Elevation View	
		W Elevation View 2002 section	
W Primary Structural Type on 2002 section		W Primary Structural Type	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Silverton Hospital

NFP - Silverton

Mari_hos01B

Building Type	County	
Hospital	Marion	
Street		
342 Fairview St		
City	State	Zip
Silverton	OR	97381
Latitude	Longitude	
45.00493	122.79003	
Tracking Code	Inspection Date	
New Building	8/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	0	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Silverton Hospital

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Silverton Hospital

Mari_hos01B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1995	1930
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: 2 to 3 Changes	
None		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		Building On Hill or Sloped Site	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
W Vertical Irregularity Tertiary		N Elevation View	
		N Plan Irregularity Primary	
			
N Elevation View		N Elevation View	
		NW Elevation View	
			
W Elevation View		W General Site MAIN ENTRY AND CONN TO NEW	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries