

| | | |
|--------------------------------|-----------------------------|--------------|
| Building Type Police - City | County Marion | |
| Street 5 Garfield St | | |
| City Mount Angel | State OR | Zip 97362 |
| Latitude 45.06769 | Longitude 122.79816 | |
| Tracking Code RVS in 2006 | Inspection Date 8/1/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | C2 | 2.8 | -1 | 0 | -1 | 0 | 0 | -0.6 | 0 | 0.2 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Mt Angel Police Dept

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| C2 | 0.2 |

FEMA-154 Collapse Potential

High (>10%)

No
Planview
Available



Oregon Geology

Mt Angel Police Dept

Mari_pol12A

| | | | |
|---|-----------------------------|--|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| | | | 1920 |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| | 1 | Yes | No |
| Plan Irregularities | | Vertical Irregularities | |
| None | | Steps in Elevation View: 2 to 3 Changes | |
| None | | None | |
| None | | None | |
| Falling Hazards | | Poor Conditions | |
| None | | None | |
| None | | None | |
| None | | None | |
|  | |  | |
| SW General Site | | W Elevation View | |
|  | | W Basement | |
|  | |  | |
| NW Other | | E Building Name | |
|  | | NW Primary Structural Type C2 | |
|  | |  | |
| NE General Site | | E Vertical Irregularity Primary | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries