

Oregon State Capitol Building

Mari_pol19A

Oregon State Police

Building Type Police - State	County Marion	
Street 900 Court St NE		
City Salem	State OR	Zip 97301
Latitude 44.93836	Longitude 123.03041	
Tracking Code RVS in 2006	Inspection Date 8/1/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.2	-1	-0.5	-1	0	-0.4	0	0	0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Oregon State Capitol Building

Final RVS Score

Final Type	Final Score
C2	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Oregon State Capitol Building

Mari_pol19A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1938	1938	1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	4	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
None		Building On Hill or Sloped Site	
None		Internal Discontinuous Diaphram (large internal opening)	
Falling Hazards		Poor Conditions	
Heavy Cladding (thick stone or concrete)		None	
None		None	
None		None	
			
S	Vertical Irregularity Primary	S	Vertical Irregularity Primary
			
		NW	Elevation View
			
N	Elevation View		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries