

Hubbard Police Dept

City of Hubbard

Mari_pol27A

Building Type Police - City	County Marion	
Street 3720 2nd St		
City Hubbard	State OR	Zip 97032
Latitude 45.18263	Longitude 122.80508	
Tracking Code RVS in 2006	Inspection Date 7/26/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	0	-1	0	0	-0.8	0	2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hubbard Police Dept

Final RVS Score


Final Type	Final Score
W2	2

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1892	1892	Pre 1900
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
3230	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		Differential Settlement with Damage	
None		Other	
None		None	
			
W Field Verified Year Built 1892		NW General Site	
		NE Building Quality brick foundation, police officer said it goes down about 6 inches.	
			
N Building Quality		NW Building Quality whole wall is sliding off foundation	
		E General Site	
			
SE General Site		S Primary Structural Type	
		NW General Site 1900 photo of building	

