

# North Marion High School

North Marion SD 15

Mari\_sch10A

Building Type	County	
School	Marion	
Street		
20167 Grim Rd NE		
City	State	Zip
Aurora	OR	97002
Latitude	Longitude	
45.21121	122.79599	
Tracking Code	Inspection Date	
RVS in 2006	7/26/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Tertiary		0	0	0	0	0	0	0	0	0

North Marion High School

## Final RVS Score

Final Type	Final Score
C2	0.7

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# North Marion High School

Mari\_sch10A

Enrollment 582	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 117456	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent) None None	
Falling Hazards Other: Ornamental Hazard Over Exit Other: Brick Veneer None		Poor Conditions Poor Concrete None None	
			
SW General Site new bldg (2000) on left. No visible seismic joint in inside or outside.	S Primary Structural Type	NE General Site new bldg wraps around front of bldg A	
			
NE General Site	SW Falling Hazard	W Falling Hazard	
			
W Falling Hazard	W Falling Hazard	SE Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



S Plan Irregularity Primary



# North Marion High School

Mari\_sch10B

North Marion SD 15

Building Type	County	
School	Marion	
Street		
20167 Grim Rd NE		
City	State	Zip
Aurora	OR	97002
Latitude	Longitude	
45.21134	122.79746	
Tracking Code	Inspection Date	
RVS in 2006	7/26/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	0	0	0	0	-0.6	0	2
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Marion High School

## Final RVS Score

Final Type	Final Score
PC1	2

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# North Marion High School

Mari\_sch10B

Enrollment 582	Year Built (Field Verified) 1971	Year Built (Alt. Source) 1950	Est. Decade Built 1970
Total Area (square ft) 117456	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions Poor Concrete None None	
			
NE Poor Condition	SE Primary Structural Type	S General Site	
			
W General Site	W General Site		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Marion High School

Mari\_sch10C

North Marion SD 15

Building Type	County	
School	Marion	
Street		
20167 Grim Rd NE		
City	State	Zip
Aurora	OR	97002
Latitude	Longitude	
45.21097	122.79565	
Tracking Code	Inspection Date	
RVS in 2006	7/26/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Marion High School

## Final RVS Score

Final Type	Final Score
W2	0.5

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

# North Marion High School

Mari\_sch10C

Enrollment 582	Year Built (Field Verified) 1950	Year Built (Alt. Source) 1950	Est. Decade Built 1950
Total Area (square ft) 117456	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
Other: Brick Veneer		None	
None		None	
			
N General Site		NE Falling Hazard glass block	
		E General Site	
			
E Falling Hazard		SE Falling Hazard	
			
NE Field Verified Year Built 1950			
			
E General Site		SW General Site	
		N General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Marion High School

North Marion SD 15

Mari\_sch10D

Building Type School	County Marion	
Street 20167 Grim Rd NE		
City Aurora	State OR	Zip 97002
Latitude 45.21037	Longitude 122.79608	
Tracking Code RVS in 2006	Inspection Date 7/26/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	0	0	-0.8	0	2.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Marion High School

## Final RVS Score

Final Type	Final Score
W2	2.5

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Marion High School

Mari\_sch10D

Enrollment 582	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1950	Est. Decade Built 1960
Total Area (square ft) 117456	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:L shaped (Adjacent Build/Entity) None None		Vertical Irregularities None None None	
Falling Hazards Other: General Other: Brick Veneer None		Poor Conditions None None None	
	SE Falling Hazard		S General Site
	S General Site		SW General Site
	SW General Site		W Building Quality



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



SW General Site



# North Marion High School

Mari\_sch10E

North Marion SD 15

Building Type	County	
School	Marion	
Street		
20167 Grim Rd NE		
City	State	Zip
Aurora	OR	97002
Latitude	Longitude	
45.2109	122.79654	
Tracking Code	Inspection Date	
RVS in 2006	7/26/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Marion High School

## Final RVS Score

Final Type	Final Score
W2	0.5

## FEMA-154 Collapse Potential

High (>10%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Marion High School

Mari\_sch10E

Enrollment 582	Year Built (Field Verified) 1969	Year Built (Alt. Source) 1950	Est. Decade Built 1960
Total Area (square ft) 117456	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) Steps in Elevation View: Single Change None	
Falling Hazards Other: Brick Veneer None None		Poor Conditions None None None	
			
SW Falling Hazard	SW General Site	NE General Site plywood siding above brick.	
			
SW General Site	SW Pounding Potential	SW General Site	
			
NE General Site	NE General Site	SW Primary Structural Type could not see columns but everything else is wood.	



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries