

Hoover Elementary School

Salem-Keizer SD 24J

Mari_sch22A

Building Type	County	
School	Marion	
Street		
1104 Savage Dr NE		
City	State	Zip
Salem	OR	97301
Latitude	Longitude	
44.94486	122.99579	
Tracking Code	Inspection Date	
SER & RVS2006	7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Hoover Elementary School

Final RVS Score

Final Type Final Score

W2 2.5

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Mari_sch22A

Enrollment 606	Year Built (Field Verified) 1968	Year Built (Alt. Source) 1968	Est. Decade Built 1940
Total Area (square ft) 52901	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
Reentrant Corners: E Shaped		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
Unreinforced Chimneys		None	
Other: Brick Veneer		None	
			
W Elevation View	W Elevation View	W Building Name	
			
SW Elevation View	S Elevation View	S Primary Structural Type	
			
SE Primary Structural Type	E Falling Hazard	E Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Mari_sch22A



E Elevation View



E Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Salem-Keizer SD 24J

Mari_sch22B

Building Type School	County Marion	
Street 1104 Savage Dr NE		
City Salem	State OR	Zip 97301
Latitude 44.94486	Longitude 122.99542	
Tracking Code SER & RVS2006	Inspection Date 7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	0	-0.5	0	2.4	0	-0.8	0	4.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Hoover Elementary School

Final RVS Score

Final Type	Final Score
W2	4.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Mari_sch22B

Enrollment 606	Year Built (Field Verified) 1968	Year Built (Alt. Source) 1968	Est. Decade Built 1980
Total Area (square ft) 52901	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:E Shaped (Adjacent Build/Entity) None None		Vertical Irregularities None None None	
Falling Hazards None None None		Poor Conditions None None None	
 SE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Salem-Keizer SD 24J

Mari_sch22C

Building Type	County	
School	Marion	
Street		
1104 Savage Dr NE		
City	State	Zip
Salem	OR	97301
Latitude	Longitude	
44.94567	122.99566	
Tracking Code	Inspection Date	
SER & RVS2006	7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

Hoover Elementary School

Final RVS Score

Final Type Final Score

W2 2.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Hoover Elementary School

Mari_sch22C

Enrollment 606	Year Built (Field Verified) 1968	Year Built (Alt. Source) 1968	Est. Decade Built 1980
Total Area (square ft) 52901	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards Other: Brick Veneer Other: Ornamental Hazard Over Exit None		Poor Conditions None None None	
			
W Falling Hazard	S Elevation View	NE Elevation View	
			
W Primary Structural Type STL ROOF TRUSSES AND SHEETROCKED WALLS			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries