

Parrish Middle School

Salem-Keizer SD 24J

Mari_sch40A

Building Type	County
School	Marion
Street	
802 Capitol St NE	
City	State Zip
Salem	OR 97301
Latitude	Longitude
44.94548	123.02429
Tracking Code	Inspection Date
RVS in 2006	7/31/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	0	-1	0	-0.4	0	0	0.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Parrish Middle School

Final RVS Score

Final Type	Final Score
C2	0.4

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parrish Middle School

Mari_sch40A

Enrollment 684	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1920
Total Area (square ft) 109522	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Single Change (Adjacent Building/Entity)	
Reentrant Corners: Other None		None	
None		None	
Falling Hazards		Poor Conditions	
Parapets: Unreinforced Over Exit		Cracks	
Other: General		None	
None		None	
			
NW Falling Hazard WALL BETWEEN BLDGS	W Field Verified Year Built	S Elevation View	
			
S Poor Condition	S Poor Condition	SE Vertical Irregularity Primary	
			
NE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parrish Middle School

Salem-Keizer SD 24J

Mari_sch40B

Building Type School	County Marion	
Street 802 Capitol St NE		
City Salem	State OR	Zip 97301
Latitude 44.94541	Longitude 123.02396	
Tracking Code RVS in 2006	Inspection Date 7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Parrish Middle School

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential


Very High (100%)



OregonGeology

Parrish Middle School

Mari_sch40B

Enrollment 684	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1940
Total Area (square ft) 109522	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent) None None	
Falling Hazards Other: Ornamental Hazard Over Exit None None		Poor Conditions None None None	
 N Elevation View		 E Elevation View	
		 SE Field Verified Year Built CONN TO D, OLD WINDOWS	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parrish Middle School

Mari_sch40C

Salem-Keizer SD 24J

Building Type	County	
School	Marion	
Street		
802 Capitol St NE		
City	State	Zip
Salem	OR	97301
Latitude	Longitude	
44.94513	123.02409	
Tracking Code	Inspection Date	
RVS in 2006	7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Parrish Middle School

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parrish Middle School

Mari_sch40C

Enrollment 684	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1940
Total Area (square ft) 109522	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other None None		Steps in Elevation View: Single Change (Adjacent Building/Entity) Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None	
Falling Hazards		Poor Conditions	
None None None		None None None	
			
S Vertical Irregularity Primary		SE Vertical Irregularity Secondary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parrish Middle School

Salem-Keizer SD 24J

Mari_sch40D

Building Type School	County Marion	
Street 802 Capitol St NE		
City Salem	State OR	Zip 97301
Latitude 44.94571	Longitude 123.02375	
Tracking Code RVS in 2006	Inspection Date 7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary	RM1	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Tertiary		0	0	0	0	0	0	0	0	0

Parrish Middle School

Final RVS Score

Final Type	Final Score
C2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parrish Middle School

Mari_sch40D

Enrollment 684	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1940
Total Area (square ft) 109522	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		Steps in Elevation View: Very Irregular Changes	
Out of Plane Lateral-Force-Resistance Elements		Steps in Elevation View: Very Irregular Changes (Adjacent Building/Ent)	
None		None	
Falling Hazards		Poor Conditions	
Other: Ornamental Hazard Over Exit		None	
None		None	
None		None	
			
NW Field Verified Year Built GLASS BLOCK	NW Vertical Irregularity Primary	NW Elevation View	
			
N Primary Structural Type NO CORNER JTS - SO PIP CONC	NE Vertical Irregularity Primary	SE Secondary Structural Type SMALL RM PART	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parrish Middle School

Salem-Keizer SD 24J

Mari_sch40E

Building Type School	County Marion	
Street 802 Capitol St NE		
City Salem	State OR	Zip 97301
Latitude 44.94541	Longitude 123.02354	
Tracking Code RVS in 2006	Inspection Date 7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Parrish Middle School

Final RVS Score

Final Type	Final Score
W2	-0.1

FEMA-154 Collapse Potential

Very High (100%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parrish Middle School

Mari_sch40E

Enrollment 684	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1920
Total Area (square ft) 109522	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 NE Elevation View			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parrish Middle School

Salem-Keizer SD 24J

Mari_sch40F

Building Type School	County Marion	
Street 802 Capitol St NE		
City Salem	State OR	Zip 97301
Latitude 44.94504	Longitude 123.02365	
Tracking Code RVS in 2006	Inspection Date 7/31/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	-0.4	0	0	1.9
Secondary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Tertiary	PC1	2.6	0	-0.5	0	0	-0.4	0	0	1.7

Parrish Middle School

Final RVS Score

Final Type	Final Score
PC1	1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Parrish Middle School

Mari_sch40F

Enrollment 684	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1990
Total Area (square ft) 109522	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SE	Plan Irregularity Primary	N	Elevation View
			
		N	Vertical Irregularity Secondary



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries