

# South Salem High School

Salem-Keizer SD 24J

Mari\_sch46A

Building Type		County	
School		Marion	
Street			
1910 Church St Se			
City	State	Zip	
Salem	OR	97302	
Latitude		Longitude	
44.9223		123.03979	
Tracking Code		Inspection Date	
Structural Engineering Report		9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C3	1.6	-1	-0.5	0	0	-0.4	0	0	-0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

South Salem High School

## Final RVS Score

Final Type

Final Score

C3

-0.3

FEMA-154 Collapse Potential

Very High (100%)

**No  
Planview  
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1925		1954	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
270050	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions